

Document Number: DPF2016082/1

Date: 05/Sep/2016

## **Overall Information**

## Table1- Overall Information

	an injerination
Vehicle plate number	78524
CPK data logger number	LN: 001443, DN: 1930,Sim +989218786219
Bus line	Number 4 (south to north Bus line)
Bus Terminals	Tehran South Bus Terminal - Park Way Bus Terminal
Total path distance	22.8 km
DPF producer company	PURItech (Passive system with FBC)
Installation date	28/Jan/2015
Report period	16/Aug/2016 – 31/Aug/2016 (sixeen days)
K value	-
K value	-

## Table 2- DPF Maintenance History

rable 2 Dri Wallechande History	
	DPF core was removed on Jul 22 <sup>nd</sup> and was
Filter maintenance date	cleaned on Aug 12 <sup>th</sup> for the first time.
	Considering system relatively high backpressure,
	filter isolation defect and air filter's deformation,
	DPF core was removed on Sep 16 <sup>th</sup> and installed on Nov 17 <sup>th</sup> .
	The third cleaning was unavoidable after only 6
	days working and was done on 29th Nov. System
	only worked for two days and DPF was replaced
	by muffler on Nov 30 <sup>th</sup> .
	DPF was installed for the fourth time on
	Jan/19/2016 and was replaced by muffler after
	only three days working because of high
	backpressure.
	A new DPF core was installed on May/14/2016
	and was cleaned on Jun/25/2016.
	The DPF core was replaced by muffler on
	Jul/10/2016 due to high backpressure.
	Jan, 10, 2010 and to mg. Duckpressure.
Dosing status	Dosing value has been kept constant from
Doding status	installation date until now.
	installation date until now.



Document Number: DPF2016082/1

Date: 05/Sep/2016

NOTE: The bus was stopped on this period due to technical problems.