

## Overall Information

*Table1- Overall Information*

Vehicle plate number	33572 (28958)
CPK data logger number	LN: 001521, DN: 1995, Sim Number +989218469643
Bus line	Number 2 (west to east bus line)
Bus Terminals	Khavaran Bus Terminal - Western Bus Terminal
Total path distance	19 km
DPF producer company	HJS_03 (active system with FBC – electrical heater)
Installation date	19/Feb/2015
Report period	16/Jan/2016 – 31/Jan/2016 (sixteen days)
K value - DPF upstream	1.90 [1/m]
K value – DPF downstream	0.02 [1/m]

*Table 2- DPF Maintenance History*

Filter maintenance date	DPF was cleaned on Oct 5 <sup>th</sup> for the first time. The second cleaning was done on Dec 19 <sup>th</sup> .
Dosing status	Dosing value has been kept constant from installation date until now.

*Table 3- Fuel and Additive Consumption Information*

Bus mileage (from DPF installation date)	47683 km
Bus mileage over the period	2634 km
Working days over the period	13 days
Stop days	3 days
Data logger working days	13 days
Working hours over the period	194 hours 44 minutes
Average working hours per day (including stop days)	12 hours 10 minutes
Bus average speed	13.52 km/hr
idle speed time to all working time ration	51.24 %
Total Bus fuel consumption over the period	1712 lit
Fuel consumption per hour	8.8 lit/hr
Average fuel consumption	0.65 lit/km
Total Bus additive consumption over the period	0.75 lit
Average additive consumption	285 cc/km
Additive consumption to fuel ration	438 cc/1000lit

### Temperature, Pressure and Engine Speed Overview




Figure 1- Pressure distribution over the working hours




Figure 2-Temperature distribution over the working hours




Figure 3- Engine speed distribution over the working hours

Table 4- Mean values

Mean temperature (C)	Mean pressure(mbar)	Mean engine speed(rpm)
212.42	25.63	747

Table 5- Mean values without idling

Mean temperature (C)	Mean pressure(mbar)	Mean engine speed(rpm)
260.01	45.44	957

Table 6- Max-min values

Max-min temperature(C)	Max-min pressure(mbar)	Max-min engine speed(rpm)
434-50	246-0	1904-496

## Detailed Pressure Analysis




Figure 4- Pressure distribution over the period




Figure 5- Pressure vs. working hours

Notice: backpressure distribution was shown into two diagrams. As obvious in figure 5, stop-working periods were eliminated and pressure was displayed along working hours.

## Detailed Temperature Analysis




Figure 6- Temperature distribution over the period






Figure 7- Temperature distribution over the period



*Figure 8- Temperature vs. working hours*



*Figure 9- Temperature vs. working hours*

## Engine Speed Diagrams




Figure 10- Engine speed distribution over the period




Figure 11- Engine speed diagram for calculating CPK's working days






Figure 12- Time diagram for calculating CPK's working days

Notice: Data logger sampling time can be calculated from Figure 12. The lines parallel with Date axis show days without data logger data. As depicted in Figure 12, data logger didn't sample on three days because bus was stationary.

### Pressure-Engine Speed diagrams




Figure 13- Pressure against engine speed




Figure 14- P, N distribution vs. working hours

### Temperature-Engine Speed diagrams




Figure 15- Temperature against engine speed




Figure 16- T, N distribution vs. working hours

### Filter Operation Analysis

- As depicted in figure 1, 0.03% of total working time pressure is above 200 mbar and 0.23% above 150 mbar during this period. This low pressure distribution was because of the cleaning issue which was done on Dec 19<sup>th</sup>.
- Figure 2 displays flow temperature distribution for DPF's upstream. It can be obviously observed 1.3% of total working time temperature is above 350°C.

Filter operation status	Excellent <input checked="" type="checkbox"/>	Good <input type="checkbox"/>
	Maintenance required <input type="checkbox"/>	Failed <input type="checkbox"/>