

Date: 18/Jul/2016

## **Overall Information**

#### Table1- Overall Information

Tables Overall Injointation		
Vehicle plate number	85476	
CPK data logger number	LN: 001508, DN: 2003, Sim +989218469624	
Bus line	Number 10 (south to north Bus line)	
Bus Terminals	Azadi square - Daneshgah square	
Total path distance	10.7 km	
DPF producer company	HJS_04 (Passive system with FBC)	
Installation date	23/Feb/2015	
Report period	01/Jul/2016 – 15/Jul/2016 (fifteen days)	
K value - DPF upstream	1.90 [1/m]	
K value – DPF downstream	0.02 [1/m]	

#### Table 2- DPF Maintenance History

Filter maintenance date	DPF was cleaned on 22 <sup>nd</sup> Jul for the first time and on 15 <sup>th</sup> Dec for the second time after 44355 km mileage from installation date.
Dosing status	Dosing value has been kept constant from installation date until now.



Date: 18/Jul/2016

Table 3- Fuel and Additive Consumption Information

Table 5- Fuel and Additive Consumption Information			
Bus mileage (from DPF installation date)	71313 km		
Bus mileage over the period	462 km		
Working days over the period	7 days		
Stop days	8 days		
Data logger working days	7 days		
Working hours over the period	27 hours 55 minutes		
Average working hours per day (including stop days)	2 hours 8 minutes		
Bus average speed	16.5 km/hr		
idle speed time to all working time ration	19.01 %		
Total Bus fuel consumption over the period	300 lit		
Fuel consumption per hour	10.7 lit/hr		
Average fuel consumption	0.65 lit/km		
Total Bus additive consumption over the period	0.143 lit		
Average additive consumption	310 cc/km		
Additive consumption to fuel ration	478 cc/1000lit		



Date: 18/Jul/2016

#### **Temperature, Pressure and Engine Speed Overview**




Figure 1- Pressure distribution over the working hours




Figure 2-Temperature distribution over the working hours



Date: 18/Jul/2016




Figure 3- Engine speed distribution over the working hours

#### Table 4- Mean values

Mean temperature (C)	Mean pressure(mbar)	Mean engine speed(rpm)
327.49	57.01	524

Table 5- Mean values without idling

Mean temperature (C)	Mean pressure(mbar)	Mean engine speed(rpm)
326.37	57.93	524

#### Table 6- Max-min values

Max-min temperature(C)	Max-min pressure(mbar)	Max-min engine speed(rpm)
602-50	270-6	1776-256



Date: 18/Jul/2016

#### **Detailed Pressure Analysis**




Figure 4- Pressure distribution over the period




Figure 5- Pressure vs. working hours

Notice: backpressure distribution was shown into two diagrams. As obvious in figure 5, stopworking periods were eliminated and pressure was displayed along working hours.



Date: 18/Jul/2016

## **Detailed Temperature Analysis**




Figure 6- Temperature distribution over the period




Figure 7- Temperature distribution over the period



Date: 18/Jul/2016




Figure 8- Temperature vs. working hours




Figure 9- Temperature vs. working hours



Date: 18/Jul/2016

# **Engine Speed Diagrams**




Figure 10- Engine speed distribution over the period




Figure 11- Engine speed diagram for calculating CPK's working days



Date: 18/Jul/2016




Figure 12- Time diagram for calculating CPK's working days

Notice: Data logger sampling time can be calculated from Figure 12. The lines parallel with Date axis show days without data logger data. As depicted in Figure 12 system was stationary for 8 days.

## **Pressure-Engine Speed diagrams**




Figure 13- Pressure against engine speed



Date: 18/Jul/2016




Figure 14- P, N distribution vs. working hours

## **Temperature-Engine Speed diagrams**




Figure 15- Temperature against engine speed



Date: 18/Jul/2016




Figure 16- T, N distribution vs. working hours

## **Filter Operation Analysis**

- As depicted in Figure 1, 0.78% of working time, pressure was above 200 mbar and 7.46% was above 150 mbar.
- Figure 2 displays flow temperature before the DPF. It can be obviously observed that 37.1% of total working time temperature is above 400 °C and 47.2% above 350°C.

Filter on eartism status	Excellent 🗆	Good ■
Filter operation status	Maintenance required □	Failed 🗆