

Date: 20/Sep/2015

Overall Information

Table1- Overall Information

	er overall injointation	
Vehicle plate number	78515	
CPK data logger number	LN: 001490, DN: 1954, Sim Number +9800000000	
Bus line	Number 4 (south to north bus line)	
Bus Terminals	Tehran South Bus Terminal - Park Way Bus Terminal	
Total path distance	22.8 km	
DPF producer company	Dinex_01 (passive system with FBC)	
Installation date	22/Oct/2014	
Report period	016/Aug/2015 – 31/Aug/2015 (sixteen days)	
K value - DPF upstream	1.24 [1/m]	
K value – DPF downstream	0.00 [1/m]	

Table 2- DPF Maintenance History

Filter maintenance date	Filter core was changed on 15/Feb/2015.
Dosing status	Dosing value was reduced by 70% on March February 15 th . (Secondary value/Initial value=0.3)



Date: 20/Sep/2015

Table 3- Fuel and Additive Consumption Information

rable 5 Taci and Marier	e Consumption injornation
Bus mileage (from DPF installation date)	46047 km
Bus mileage over the period	3092 km
Working days over the period	15 days
Stop days	1 day
Data logger working days	15 days
Working hours over the period	208 hours 15 minutes
Average working hours per day (including stop days)	13 hours 1 minutes
Bus average speed	14.85 km/hr
idle speed time to all working time ration	53.91 %
Total Bus fuel consumption over the period	2000 lit
Fuel consumption per hour	9.6 lit/hr
Average fuel consumption	0.65 lit/km
Total Bus additive consumption over the period	0.51 lit
Average additive consumption	164 cc/km
Additive consumption to fuel ration	255 cc per 1000 lit (continuous dosing)



Date: 20/Sep/2015

Temperature, Pressure and Engine Speed Overview




Figure 1- Pressure distribution over the working hours




Figure 2-Temperature distribution over the working hours



Date: 20/Sep/2015




Figure 3- Engine speed distribution over the working hours

Table 4- Mean values

Mean temperature (C)	Mean pressure(mbar)	Mean engine speed(rpm)
269.42	30.16	825

Table 5- Mean values without idling

Mean temperature (C)	Mean pressure(mbar)	Mean engine speed(rpm)
323.75	54.07	1146

Table 6- Max-min values

Max-min temperature(C)	Max-min pressure(mbar) Max-min engine spec	
574-50	285-0	2352-512



Date: 20/Sep/2015

Detailed Pressure Analysis




Figure 4- Pressure distribution over the period




Figure 5- Pressure vs. working hours

Notice: backpressure distribution was shown into two diagrams. As obvious in figure 5, stopworking periods were eliminated and pressure was displayed along working hours.



Date: 20/Sep/2015

Detailed Temperature Analysis




Figure 6- Temperature distribution over the period




Figure 7- Temperature distribution over the period



Date: 20/Sep/2015




Figure 8- Temperature vs. working hours




Figure 9- Temperature vs. working hours



Date: 20/Sep/2015

Engine Speed Diagrams




Figure 10- Engine speed distribution over the period




Figure 11- Engine speed diagram for calculating CPK's working days



Date: 20/Sep/2015




Figure 12- Time diagram for calculating CPK's working days

Notice: Data logger sampling time can be calculated from Figure 12. The lines parallel with Date axis show days without data logger data. As depicted in Figure 12, Aug 27th was stop day.

Pressure-Engine Speed diagrams




Figure 13- Pressure against engine speed

Notice: Red alarm (pressure>200 mbar) and yellow alarm (200>pressure>150) ranges were indicated in figure 13.



Date: 20/Sep/2015




Figure 14- P, N distribution vs. working hours

Temperature-Engine Speed diagrams




Figure 15- Temperature against engine speed



Date: 20/Sep/2015




Figure 16- T, N distribution vs. working hours

Filter Operation Analysis

- As depicted in figure 1, 0.71% of working time pressure was above 200 mbar and only 2.49% above 150mbar.
- Figure 2 displays flow temperature distribution for DPF's upstream. It can be obviously observed that 13% of total working time, temperature is above 400 °C and 22% above 350°C.

Filter eneration status	Excellent 🗆	Good ■
Filter operation status	Maintenance required □	Failed□